



Fuze Projector (De-armor) AME-02

In EOD avoiding detonation of unexploded bombs is the prime objective. Render Safe Procedures are adopted for which different tools are available for breaking the detonation train by attaching the bomb fuze.



Fuze projector or a De-armor deal with the fuzes of UXOs for breaking its detonation train. De-armor has specially designed barrel, with slugs to be fired by a cartridge. De-armers disrupt fuses with cocked strikers. Electric 0.5" cartridges or de-bulleted 0.5 " rounds are used in it. A fork can be used for a lower velocity attack on some specific fuses. This tool can also used against Improvised Explosive Devices (IED's) also with special shot load.